

General Environmental Incident Summary

Incident: 3382 **Date/Time Notice:** 7/14/2014 13:18 **DEM Incident No:**
Responsible Party: Baker Hughes
Date Incident: 6/28/2014 **Time Incident:** 1418 **Duration:** 1 days
County: Stark **Twp:** 140 **Rng:** 96 **Sec:** 27 **Qtr:**
Lat: 46.91585 **Long:** -102.78970 **Method:** Interpolation from map
Location Description: 272 34th Street, Dickinson ND

Submitted By: Adryan Law **Affiliation:**
Address: 6205 Chapel Hill Boulevard
suite 100
City: Plano **State:** TX **Zip:** 75093

Received By:

Contact Person: Adryan Law
17021 Aldine Westfield
Houston, TX

Distance Nearest Occupied Building: 50 Feet **Release Contained:** Yes

Type of Incident: Sewage Accident

Description of Released Contaminant: drilling Mud

Volume Spilled: 165.00 gallons **Ag Related:** Yes

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** No

Cause of Incident:

While handling the equipment Drilling Mud was released from the hose.

Risk Evaluation:

NA

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Impacted top soil (was excavated and replaced with clean soil).

Action Taken or Planned:

The crew excavated the impacted soil and placed granular absorbents on the impacted concrete. The crew utilized a vacuum truck to power washed the impacted concrete and collect the spent material and water.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/21/2014 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

The weather was 74°F, cloudy, with wind from the northwest 5 mph. The drilling mud flowed from the spill area to the east. Some of the mud hit soil around the storm water pond. This area is cleaned up, and the impacted soil has been hauled away. New erosion control mats were placed on the area where soil was cleaned up; everything looks good. No further followup needed at this time.

Date: 7/21/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

County, township, range and section were incorrect in incident summary.

Correct location is in Stark County.

272 34th Street West, Dickinson, North Dakota 58601

Twp-Rng-Sec = 140-96-27

Latitude: 46.915853

Longitude: -102.789733

Info has been corrected in incident summary.

Date: 7/21/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

According to the incident summary, this spill impacted the surrounding area. More followup is necessary.